

Client: Example Client ABC123

123 Test Drive

Salt Lake City, UT 84108

Physician: Doctor, Example

UNITED STATES

Patient: Patient, Example

DOB 10/23/1970

Sex: Female

Patient Identifiers: 01234567890ABCD, 012345

Visit Number (FIN): 01234567890ABCD **Collection Date:** 01/01/2017 12:34

Copper, Serum or Plasma

ARUP test code 0020096

Copper, Serum/Plasma

113.3 ug/dL

(Ref Interval: 80.0-155.0)

INTERPRETIVE INFORMATION: Copper, Serum or Plasma

Elevated results may be due to skin or collection-related contamination, including the use of a noncertified metal-free collection/transport tube. If contamination concerns exist due to elevated levels of serum/plasma copper, confirmation with a second specimen collected in a certified metal-free tube is recommended.

Serum copper may be elevated with infection, inflammation, stress, and copper supplementation. In females, elevated copper may also be caused by oral contraceptives and pregnancy (concentrations may be elevated up to 3 times normal during the third trimester).

This test was developed and its performance characteristics determined by ARUP Laboratories. It has not been cleared or approved by the US Food and Drug Administration. This test was performed in a CLIA certified laboratory and is intended for clinical purposes.

| VERIFIED/REPORTED DATES | | | | |
|-------------------------|---------------|---------------------|---------------------|---------------------|
| Procedure | Accession | Collected | Received | Verified/Reported |
| Copper, Serum/Plasma | 22-035-119171 | 2/4/2022 5:29:00 PM | 2/4/2022 8:46:57 PM | 2/7/2022 8:30:00 AM |

END OF CHART

H=High, L=Low, *=Abnormal, C=Critical